


LabTool-48XP / 48UXP Security Error Update Processes



(AEC) Advantech Equipment Corp.
(Step 4 & 5 & 12 by AEC)

Customer's LT-T400 S/N (AE0409000001)
(Step 1 to 3 & 6 to 11 by Customer)

PC's OS : (1) Win2000 + SP4 recommended
(2) WinXP + SP1 recommended
(3) WinXP + SP2 recommended